

POOLE HARBOUR COMMISSIONERS LOCAL NOTICE TO MARINERS POOLE HARBOUR

No. 12/2017 3rd May 2017

Rockley Channel East Cardinal Beacon

•			

Mariners are advised that the East Cardinal Beacon at the entrance to the Rockley Channel is currently off station and an underwater obstruction may exist.

The Position of the possible obstruction is: 50° 42.820N

This Notice Supersedes LNTM 10/2017

002° 01.940W

This position is marked by a yellow special mark with a light characteristic FI(2)Y.5s

Mariners should navigate this area with extreme caution.

All vessels should monitor VHF channel 14.

Mariners are reminded that Radar, AIS, CCTV, telephone and VHF channels are recorded.

<u>Captain B P Murphy</u> Harbour Master

ALL LOCAL NOTICES TO MARINERS ARE AVAILABLE ON THE PHC WEBSITE: www.phc.co.uk