


## POOLE HARBOUR COMMISSIONERS LOCAL NOTICE TO MARINERS POOLE HARBOUR

No. 28/2017 7th September 2017

## **South Quay Development Special Mark**

Mariners are advised that a special mark has been placed South East of the South Quay Development, in Position 50° 42.4333N 001° 59.1433W and has a light characteristic Fl(2)Y.5s

This buoy marks the corner of the construction works and vessels should not pass between the buoy and the quayside.



Mariners should navigate this area with extreme caution passing at slow speed with minimum wash.

Mariners are reminded that Radar, AIS, CCTV, telephone and VHF Channels are all recorded.

CAPTAIN BRIAN MURPHY HARBOUR MASTER

ALL LOCAL NOTICES TO MARINERS ARE AVAILABLE ON THE PHC WEBSITE: www.phc.co.uk